

# Release Notes for Zebra TC20 and TC25 Android Oreo 01-28-07.00-ON-U18-STD Release (Non-GMS)

## **Highlights**

The details of the Android Non-GMS Oreo release 01-28-07.00-ON-U18-STD that covers TC20/TC25. Please see, Device Compatibility under Addendum Section for more details.

#### **Software Packages**

Package Name	Description
IRIS_DELTA_UPDATE_01-28-07.00-ON-U18.zip	Delta Package Update

#### **Security Updates**

This build is Compliant up to Android Security Bulletin of April 5 2021.

#### LifeGuard Update 18:

This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.

S.N.	Component	Version
1.	Mx version	9.4.0.5
2	MX Proxy Framework	10.3.0.18
3	OSx version	QCT_81_8.13.4.UL
4	Webview	89.0.4389.90

#### LifeGuard Update 13:

This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.

S.N.	Component	Version
1.	OemInfo	9.0.0.331
2.	Wifi	FUSIONLITE_QA_1_0.0.028_O
3.	Radio	QA_1_00.0.022_0
4.	Application	QA_1_00.0.009_O
5.	Middleware	QA_1_00.0.014_O

#### LifeGuard Update 11:

This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.



S.N.	Component	Version
1.	WebView	85.0.4183.101
2.	OemInfo	9.0.0.282

#### Features

 Added support in OemInfo to allows customer applications and sideloaded applications to read BT MAC address

#### LifeGuard Update 09:

This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.

S.N.	Component	Version
1.	Android security patch level	October 5, 2020

#### LifeGuard Update 07:

This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.

S.N.	Component	Version
1.	Scanning Framework	23.1.9.1
2.	Zebra Data Service	7.0.2.1047
3.	OemInfo	9.0.0.198

#### **Fixes**

• SPR40287 – Added updates on feature dotcode bar-codes.

#### LifeGuard Update 05:

This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.

S.N.	Component	Version
1.	MX	9.4.0.2
2.	Data Wedge	7.3.34
3.	Stage Now-Client	3.4.1.5
4.	EMDK for Android	7.3.23.2323
5.	MX Proxy Framework	10.0.1.1
6.	OSx	QCT.81.8.11.4.UL

#### **Fixes**



• SPR40193/40250 – Resolved an issue wherein user was unable to power off the device by clicking on the Power menu item while automation suite was running on the device.

#### LifeGuard Update 03:

- This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.
  - FUSIONLITE\_QA\_1\_0.0.0.027\_O Radio: QA\_1\_00.0.021\_O Application: QA\_1\_00.0.009\_O Middleware: QA\_1\_00.0.0.014\_O

#### **Fixes**

• SPR39819 – Resolve an issue where EXTRA Enter was observed in app's multiline input field on scan the barcode with DW settings have set Action Key Char as "Line Feed".

#### LifeGuard Update 02:

- This LG patch is applicable for 01-28-07.00-ON-U00-STD BSP version. The LG Patch includes the following updated components.
  - FUSIONLITE\_QA\_1\_0.0.0.026\_O Radio: QA\_1\_00.0.0.020\_O Application: QA\_1\_00.0.0.009\_O Middleware: QA\_1\_00.0.0.013\_O

#### **Fixes**

- SPR38643 Added support for "Send Characters As Events" option.
- SPR38723 Resolved an issue wherein the DST time zone for Sao Paolo was shown incorrect.

#### Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	01-28-07.00-ON-U18-STD
Android Version	8.1.0
Security Patch level	April 5, 2021



Linux Kernel	3.18.71
Component Versions	Please see Component Version under Addendum section

## **Installation Instructions**

#### Software update procedure

The installation instructions assume user has ADB installed on their PC (the adb drivers etc..) and user device has developer options enabled and USB debugging ON. Please check following link for more information on installation and setup instructions.

Installation and setup instructions

#### NOTE:

For Enterprise Mobile Device Management, most EMM vendors such as SOTI, AirWatch, MobileIron, etc. WILL require an updated device management agent to support this OREO enterprise device. Do NOT use your existing device management agent and console with this device without first contacting your EMM vendor to understand when the agent supporting this device is available and whether a console upgrade is required as well. Attempting to enroll with an agent that is not validated to support the device will result in errors.

### Addendum

#### **Device Compatibility**

This software release has been approved for use on the following devices.

#### TC20 Home Page

TC20	
Device Part Number	Operating System
TC200J-20C112CN	Android O (Non-GMS Only) China Only
TC200J-20A111CN	Android O (Non-GMS Only) China Only
TC200J-2KC111CN	Android O (Non-GMS Only) Keyboard SKU - China Only
TC200J-2KC11112	Android O (Non-GMS Only) China Only
TC200J-20C213CN	Android O (Non-GMS Only) Premium SKU -China Only

#### **TC25 Home Page**

	TC25
Device Part Number	Operating System



TC25CJ-20B101CN	Android O (Non-GMS Only) China Only
TC25CJ-20C102CN	Android O (Non-GMS Only) China Only

### **Component Versions**

For detailed release notes, please refer techdocs.zebra.com, developer.zebra.com

Component / Description	Version
Build_version	01-28-07.00-ON-U18-STD
Android_version	8.1.0
Android_SDK_Level	27
Android Security Patch Level	April 5, 2021
Linux_kernel	3.18.71
	FUSIONLITE_QA_1_0.0.028_O
	Radio: QA_1_00.0.022_O
	Application: QA_1_00.0.009_O
	Middleware: QA_1_00.0.014_O
Wifi	Firmware: CNSS-PR-4-0-00713/01050102
Platform	Qualcomm MSM8937
Scanning_Framework	23.1.9.1
DWDemo	2.0.15
OSX	QCT.81.8.13.4.UL
MXMF	9.4.0.5
Touch	Focaltech V1.1 20161103 (fw:0x24)
Acoustic Profiles	General: CO4.2
	Cellular: CO4.2
Bluetooth_Stack	CNSS-PR-4-0-00713/01050102
Flash_Size	16G /32G
RAM_Size	2G
GPS	MPSS.JO.3.0.c13-00016-8937_GENNS_PACK-1
MMS	8.1.0
RIL_Version	Qualcomm RIL 1.0
BT_Pairing_Utility	3.15



Datawedge	7.3.34
Camera	2.0.002
РТТ	3.1.39
RxLogger	5.4.12.0
StageNow	3.4.1.5
Zebra Data Service	7.0.2.1047
Zebra Software License Manager	3.2.0
EMDK	7,3,23,2323
IMEI SV Number	11
OEM Config	9.0.0.331
DDT	V1.17.0.9
WebView	89.0.4389.90
Fingerprint	Zebra/TC25/TC25FM:8.1.0/01-28-07.00-ON-U18- STD/210331:user/release-keys,   Zebra/TC20/TC20RT:8.1.0/01-28-07.00-ON-U18- STD/210331:user/release-keys,   ZebraTC20/TC20RD:8.1.0/01-28-07.00-ON-U18- STD/210331:user/release-keys,   ZebraTC20/TC20KB:8.1.0/01-28-07.00-ON-U18- STD/210331:user/release-keys,   Zebra/TC20/TC20KB:8.1.0/01-28-07.00-ON-U18- STD/210331:user/release-keys,

### **Important Links**

- https://techdocs.zebra.com/datawedge/7-3/guide/about/
- https://techdocs.zebra.com/emdk-for-android/7-3/guide/about/
- https://techdocs.zebra.com/stagenow/3-4/about/
- https://techdocs.zebra.com/mx/
- https://techdocs.zebra.com/ddt/1-1/guide/about/
- https://techdocs.zebra.com/rxlogger/5-4/guide/about/

## **Known Issues and Workarounds**

- OS downgrade behavior has changed in Oreo. Automatic enterprise data reset is performed when the system detects OS downgrade operation. Following are the examples of OS downgrade operations:
  - Oreo (NGMS) to Nougat (NGMS)
  - Downgrading to lower patch version within Oreo.
- To avoid text cropping in some applications, accessibility options can be used to change the display size to small.
- An issue wherein period key was not working on Remote connections (RDP / Horizon / Citrix) User needs to push an empty file namely SPR36457.txt and copy it into /enterprise/usr/persist/ and reboot the device for this functionality to get enabled.



# **Revision History**

REV	DESCRIPTION	DATE
1.0	Initial Release	April 16, 2021