# Release Notes – TC55 Android JB – GPS Rollover Fix Release for Non-GMS

## Contents

Introduction

**Description** 

**Component Version** 

Package Details

**Device Compatibility** 

**Installation Requirements** 

Installation Instructions

Release Date

#### Introduction

This release contains the GPS Rollover fix software package which is compatible for TC55 JB Non-GMS following BSP version.

BSP Version
1.79NG
01.77NG
01.74NG

SPR37323\_TC55\_JB\_Non-GMS\_GPSRollover\_Fix.zip

### **Description:**

Updated to handle extended GPS Week number for correct date calculation due to GPS week number roll over

# **Component Version:**

Component / Description	Version
GPS Version	1.0.1

## Package Details

SPR37323\_TC55\_JB\_Non-GMS\_GPSRollover\_Fix.zip

# **Device Compatibility**

This software release has been approved for use with the following Zebra devices.

Device	OPERATING System
TC55	JB 4.1.2

## Installation Requirements

This SW is intended for all the TC55 JB devices only.

- ADB installed on the PC (including adb drivers)
- USB debugging turned ON (from Developer options)

#### Installation Instructions

- 1. Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.
- On your PC, you should see an internal and external USB mass storage drive (SD card)
  appears in the File Explore and copy "SPR37323\_TC55\_JB\_Non-GMS\_GPSRollover\_Fix.zip" file
  to any storage.
- 3. Press and hold on the device the Power button, Scan/Action button and Vol+ until the screen is turned OFF.
- 4. Release the Power and Scan/Action buttons and continue to hold Vol+ button.
- 5. The device should enter to Recovery update mode.
- 6. Release Vol+.
- 7. Click on Vol+ or Vol- to navigate and select appropriated storage.

- 8. Click on Scan/Action button to select the option.
- 9. Click on Vol+ or Vol- to navigate to the patch file.
- 10. Click on Scan/Action button to select the patch file.
- 11. Device will automatically reboot and will be ready to use.
- 12. There is way to Check After installed the SPR37323\_TC55\_JB\_Non-GMS\_GPSRollover\_Fix.zip patch in the device.
  - ➤ About Phone->SW components->Gps: 1.0.1

#### **Release Date**

Oct 2019