

# Release Notes – Zebra Android 11

## 11-27-16.00-RN-U00-STD-ATH-04 Release (NGMS)

### Highlights

This Android 11 NGMS release 11-27-16.00-RN-U00-STD-ATH-04 covers TC53 family of products.

Please see device compatibility under Addendum Section for more details.

### Software Packages

Package Name	Description
AT_FULL_UPDATE_11-27-16.00-RN-U00-STD-ATH-04.zip	Full package update
ATH_DELTA_UPDATE_11-25-02.00-RN-U00-STD_TO_11-27-16.00-RN-U00-STD.zip	Delta package update from 11-25-02.00-RN-U00-STD to 11-27-16.00-RN-U00-STD release  <b>Applicable for TC53 SKUs</b>

### Security Updates

This build is Compliant up to [Android Security Bulletin](#) of **October 01, 2023**

•

### LifeGuard Update 11-27-16.00-RN-U00

➤ This LG patch is applicable for 11-27-16.00-RN-U00-STD-ATH-04 BSP version.

#### ○ New Features

- Added MX PowerMgr support for Zebra Recovery Protection.
- Added a new MX 13.1 UiMgr feature, which provides the capability to allow/block inter-app sharing, which will allow an app on the device to share data with other apps on the device.
- Added a new MX feature which allows to configure,
  - Two applications which are to be launched in split screen mode in a customized split ratio automatically after reboot.
  - Single application to be launched in full screen mode automatically after reboot.”
- Added OEMInfo support to programmatically retrieve battery information (ex. battery level, health, model, etc) of connected BT peripherals (ex: supported Zebra Bluetooth scanners and HS3100 headset) using OEMInfo content provider URI.
- Added Datawedge support for MP7X Scale (weight).

- Added Datawedge support for new picklist + OCR feature, which allows capture of either a barcode or OCR (single word) by centering the desired target with the aiming crosshair or dot. Supported on both Camera and Integrated Scan Engines.
- Added OEMInfo support for Partnumber content provider URI supporting API for HW SKU.
- Added new firmware for SE55 Scan Engine to improve autofocus.
- Added a new mechanism to handle a crash in WLAN Firmware.

#### ○ Resolved Issues

- SPR-50931 - Resolved an issue where Datawedge Free form OCR data formatting support has been added for the keystroke output.
- SPR-50778 –Resolved an issue where StageNow profile to install apk with capital APK fails.
- SPR-48863 - Resolved an issue where OEMConfig Clock Settings was not being applied for Auto time mode.
- SPR-51046 - Resolved an issue wherein pfx certificate will not import correctly via StageNow.
- SPR-50649 – Resolved an issue wherein intent is not passed to app even scanning barcode after Suspend/Resume.
- Resolved issue where Android data folder is not viewable via Files app.

#### ○ Usage Notes

- None

### LifeGuard Update 11-25-02.00-RN-U00

- This LG patch is applicable for 11-25-02.00-RN-U00-STD-ATH-04 BSP version.

#### ○ New Features

- None

#### ○ Resolved Issues

- SPR-50146 - Resolved an issue wherein any key remap to the Power key was not working.
- SPR-50667 - Added reconnection support for Legacy BT devices with Security Mode 3
- SPR50566 - Adjusted acoustic profiles based on the comparison with TC52x volume level to improve the audio throughput.
- SPR-50233 - Fixed an issue with accelerometer sensor events not coming regularly due to camera interference with the sensor data.
- SPR-50817 - Fixed an issue where device with extremely depleted battery would not charge on charge only dock.

#### ○ Usage Notes

- None

### LifeGuard Update 11-21-27.00-RN-U00

➤ This LG patch is applicable for 11-21-27.00-RN-U00-STD-ATH-04 BSP version.

### ○ New Features

- Added support of BtInsights v2.0 API for paired Bluetooth peripheral.
- Added support MX CSP 11.9 for WWAN/LAN connection Manager.
- Added support for MX UI CSP Setting RecentApp Button/Home Key/Long Press on Home Key features for Gesture Navigation.
- Initial Beta Release of Zebra Showcase App (Self Updatable) explores the latest features and solutions, a platform for new demos built on Zebra Enterprise Browser.
  - DWDemo has moved to the ZConfigure folder.

### ○ Resolved Issues

- Resolved an issue wherein KeyEventService was not sending intent when a key was remapped to send Intent.
- SPR48429 - Resolved issue where quick settings was accessible in Reduced settings mode when battery saver is turned on.
- SPR48826 – Resolved an issue wherein notification bar was big in size.
- SPR48066 – Resolved an issue wherein avc related log msgs were filling up the Rxlogger logs.
- SPR50161 – Ping loss Due to Device going to suspend and taking delay in reconnection.
- SPR48045 - Resolved an issue wherein MX not able to use host manager & host name.

### ○ Usage Notes

- None

## LifeGuard Update 11-19-15.00-RN-U00

➤ This LG patch is applicable for 11-19-15.00-RN-U00-STD-ATH-04 BSP version.

### ○ New Features

- Added a new MX new feature that controls whether to allow all USB peripherals to be used when the device is in USB Host Mode or to restrict usage to peripherals as defined in Rules created by the administrator using the Control Rules parameter.
- Added a new MX new feature that allows to run applications automatically upon connecting USB devices by suppressing the pop-up confirmation triggered by the Android system, if the application is marked as an auto launch application for the connected USB device.
- DataWedge:
  - New viewfinder functionalities to vision features (Camera only)
    - Zoom(1x/2x/4x/8x) button
    - Illumination(on/off) button
    - Pinch and zoom
  - Added a programmatic method to retrieve KeyStates on Keyboard enabled devices (SHIFT) (SPR 47506/47368).
  - Improved indoor navigation use cases.

### ○ Resolved Issues

- SPR47143 - Resolved an issue wherein few additional log messages were enabled in NFC component.
- SPR47950 - Resolved an issue wherein Short Press of key was showing Power Menu.
- SPR47868 - Resolved an issue where sometimes WIFI-WWAN transition was not working.
- SPR48699 - Resolved Wi-Fi connectivity issues seen with some Cisco infrastructures where in AP did not advertise Power Constraint information and only DTPC is enabled.
- Performance enhancements and bug fixes in OCR Wedge.

### ○ Usage Notes

- None

## LifeGuard Update 11-17-16.00-RN-U00

- This LG patch is applicable for 11-17-16.00-RN-U00-STD-ATH-04 BSP version.

### ○ New Features

- DataWedge:
- New Workflow: Free-Form OCR via Camera powered by Google ML Kit using Text Recognition v2 (Beta) API.
- Return state/country in OCR Wedge License Plate results.
- Zebra USB and Bluetooth scanner cradle support with Workstation Cradle.
- Bluetooth Pairing Utility:
- Modify size of BT pairing barcode based on screen size/resolution.
- Remove Search Magnifying Glass from Settings: Phase-2
- WorryFree WiFi (SmartMU)
- Enable/Disable Charging LED light while device is being charged
- Ability to disable the on-screen mute option in Zebra Volume Control (ZVC)
- Eliminate SD Card Pop Up

### ○ Resolved Issues

- OCR and Image capture options (Workflow input) are grayed out on DataWedge when Android Device screen lock is enabled. If OCR Wedge or Free-form Image Capture Workflow feature is required in conjunction with a device pin, it is recommended to continue to use the prior release until the next release. For Document Capture Workflow, a hot fix will be available shortly. Please contact your account team for details
- SPR47910- Resolved an issue where sometimes device enters Rescue Party mode.
- SPR47607 - Resolved an issue where device sometimes unable to resolve server names that are fully qualified domain names.

### ○ Usage Notes

- None

## Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	11-27-16.00-RN-U00-STD-ATH-04
Android Version	11
Security Patch level	October 01, 2023
Component Versions	Please see Component Versions under Addendum section

## Device Support

The products supported in this release are TC53 family of products.

Please see device compatibility details under Addendum Section.

## Known Constraints

- Delta OTA packages are not supported in Recovery mode. To apply Delta OTA packages, use StageNow/MDM solution.
- Key programmer configuration is lost after performing OS update.
- During Battery True Swap device may suspend before 30 seconds with some EMM Kiosk mode Launchers.
- User will not be able to push files into below listed directories using adb command. Alternately, EMM clients or StageNow can be used to push files into below listed directories.
  - /enterprise/

## Important Links

- [Installation and setup instructions](#) (If the link does not work, please copy It to browser and try)
- [Zebra Techdocs](#)
- [Developer Portal](#)

## Addendum

### Device Compatibility

This software release has been approved for use on the following devices.

Device Family	Part Number		Device Specific Manuals and Guides
TC53	TC5301-0T2K6B1000-CN		<a href="#">TC53</a>

## Component Versions

Component / Description	Version
Linux Kernel	5.4.210-qgki
AnalyticsMgr	10.0.0.1002
Android SDK Level	30
Audio (Microphone and Speaker)	0.18.0.0
Battery Manager	1.4.80.00
Bluetooth Pairing Utility	3.29
Camera	2.0.24
Chromium and Android Webview	116.0.5845.114
DataWedge	11.4.310
EMDK	11.0.141.4041
Files	11
License Manager and LicenseMgrService	6.1.1 and 6.1.7.5.0.3
MXMF	13.1.0.14
NFC FW	12.50.9
OEM info	9.0.0.828
OSX	QCT6490.110.11.10.30
Rxlogger	7.0.5.19
Scanning Framework	37.9.25.0
StageNow	11.9.0.1
WLAN	Fusion Version: FUSION_QA_4_1.2.0.022_R FW: 1.1.2.0.904.4
Zebra Bluetooth	11.8.1
Zebra Volume Control	3.0.0.91
Zebra Data Service	10.0.4.1263
Zebra Device Manager	13.1.0.25

WorryFreeWiFi	WA_A_3_1.1.0.024_R
---------------	--------------------

### Revision History

Rev	Description	Date
1.0	Initial release	October 03, 2023