

Release Notes – Zebra Android 10

10-12-13.00-QN-U30-STD-HEL-04 Release (NGMS)

Highlights

This Android 10 NGMS release 10-12-13.00-QN-U30-STD-HEL-04 covers TC21, TC26, TC52X, TC52 family of products. Please see, device compatibility under Addendum Section for more details.

Software Packages

| Package Name | Description |
|---|---|
| HE_DELTA_UPDATE_10-12-13.00-QN-U30-STD-HEL-04.zip | Diff package update from 10-12- 13.00-QN-U00-STD-HEL-04 |
| HE_EnterpriseReset_A10_V2.zip | Reset Package to Erase User Data Partition Only |
| HE_FactoryReset_A10_V2.zip | Reset Package to Erase User Data and Enterprise Partitions |

Security Updates

This build is Compliant up to Android Security Bulletin of September 01 2020.

Version Information

Below Table contains important information on versions

| Description | Version |
|----------------------|--|
| Product Build Number | 10-12-13.00-QN-U30-STD-HEL-04 |
| Android Version | 10 |
| Security Patch level | September 1, 2020 |
| Linux Kernel | 4.4.205 |
| Component Versions | Please see Component Versions under Addendum section |



Device Support

This software release has been approved for use on the following devices.

| Device Family | Part Number | | Device Specific Manuals and Guides |
|------------------|--------------------------------------|--------------------------------------|---------------------------------------|
| TC21 | TC210K-02A222-CN TC210K-02B212-CN | TC210K-02B412-CN TC210K-06B224-CN | TC21 Home Page |
| TC26 | TC26CK-12A222-CN TC26CK-12B212-CN | TC26CK-16B224-CN | TC26 Home Page |
| TC52X | TC520K-1XFMU6P-CN | | |
| TC52 | TC520K-2PEZU4P-CN | | TC52 Home Page |
| TC52 HC | TC520K-2HEZU4P-CN | | TC52 HC Home Page |



New Features

- Support for Single Pairing over Bluetooth.
- Support for Trusted Device Pairing over Bluetooth.
- Bluetooth Smart Leash feature: Simple audio alert and a notification message on the mobile device to indicate BT accessory is "unleashed".
- Integrated Video-On-Device application.
- Feature to restrict PTT to certain countries per regulatory requirements.
- Support for "Signature Presence Validation" with Anchored Mode Document Capture".
- Support for Edge-detect Document Capture.
- Support for WPA3
- Support for 802.11mc (Wi-Fi RTT) in premium products. Not supported in Value Tier products.
- Support for 802.11v.
- Support for WorryFree WiFi Roam and Voice Analysis
- Support for USB-C Digital Audio 3.5mm Adapter with PTT Button
- Support for Data Centric Domain Selection
- Support for Cell broadcast for Saudi and UAE regions

Resolved Issues

- Fixed: 39238 Upgraded the Chromium browser version.
- Fixed: 40770 Standardized the thermal mitigation notification across WAN products.
- Fixed: 40408 WAN disconnecting at higher temperatures.
- Fixed: 40025 Removed Imager mode options from Datawedge.
- Fixed: 38970 Batteryswap function not working with certain client applications running in foreground.
- Fixed: 40239 EMC devices without camera fail to enroll into Microsoft Intune from welcome screen
- Fixed: 40709 DW profile with BDF "sent Enter key" enabled works inconsistently.
- Fixed: 40655 On selecting DataWedge as a keyboard from the device virtual keyboard settings and disabling Google GBoard, it does not display scanned data.
- Fixed: 40544 DW fails to show notifications for subsequent connections after initial connection to DS3678.
- Fixed: 40404 EthernetMgr CSP BypassProxy does not accept wildcard on IP.
- Fixed: 40500 Custom APN setting persistence after upgrade
- Fixed: 40382 StageNow Error while Creating DSDS setting in CellularMgr

Usage Notes

None



Known Issues

- Picture quality of the image taken with 'Night Mode' in low-light conditions is poor.
- Trigger Modes: Presentation Read Mode is preferred over Continuous Read Mode. If using Continuous Read mode, use a lower illumination brightness setting (e.g. 2) to ensure the scanner can work without interruption.
- "Red Eye Reduction" feature disables the camera flash in the device. Hence, to enable the camera flash please disable the 'Red Eye Reduction' feature.
- EMM does not support agent persistence in OS dessert downgrade scenario.
- Reset packages of Oreo and Pie should not be used on devices running with A10 software.
- In-order to avoid any inconsistencies in Settings UI it is recommended to wait for a few seconds after the device boots up.
- On a device with encrypted SD card as portable storage, when a user reboots the device, it reboots more than once.
- If a mobile device connected to a DS3678/LI3678 BT Scanner is rebooted, then DS3678/LI3678 in the vicinity of EMC device fails to connect automatically.
- Thermal warning notification is not seen when TC26 device reaches upper WAN shutdown temperature threshold
- Transparent blue overlay in camera view –numeric, character or ENTER key presses in camera view will
 make this blue overlay appear. The camera is still functional; however, the view is covered with the blue
 overlay. To clear this, press the TAB key to move the control to a different menu item or close the camera
 app.
- In case of an OS upgrade from a s/w version having higher security patch level to a s/w version having lower security patch level, user data will be reset.

Important Links

- Installation and setup instructions (if the link does not work please copy It to browser and try)
- Zebra Techdocs
- Developer Portal



Addendum

Component Versions

| Component / Description | Version |
|-----------------------------------|--|
| Acoustic Profiles | TC21: General: SQ1.7 Cellular: N/A TC26: General: SQ2.7 Cellular: SQ2.7 TC52x: General: TQ1.2 Cellular: N/A TC52: General: GQ1.2 Cellular: N/A TC52HC: General: GQ2.2 Cellular: N/A TC21HC: General: SQ3.1 Cellular: N/A TC26HC: General: SQ4.1 Cellular: SQ4.1 |
| AnalyticsMgr | 2.4.0.1254 |
| Android SDK Level | 29 |
| Audio (Microphone and Speaker) | 0.26.0.0 |
| Battery App | 1.1.7 |
| Bluetooth Pairing Utility | 3.18 |
| Camera | 2.0.002(21-00) |
| DataWedge | 8.2.53 |
| EMDK | 8.2.4.2804 |
| FILES | 10 |
| License Manager and License Agent | version 4.1.1 and version 4.1.0.4.0.0 |
| MXMF | 10.2.0.29 |
| NFC | NFC_NCIHALx_AR18C0.a.3.0 |
| OEM info | 9.0.0.226 |
| OSX | QCT. 100.10.5.49 |
| RXlogger | 6.0.4.0 |
| Scanning Framework | 28.2.8.0 |



| StageNow | 5.0.0.1 |
|------------------|--|
| Touch Panel (FW) | 06 (TC21) 06 (TC26) 1.8.3-Finger-2-0:0x68cffa (TC52 HC) 0.8.1-Finger-4-0:0x39c6fa (TC52x) 1.8.3-Finger-2-0:0x68cffa (TC52) 1.8.3-Finger-2-0:0x68cffa (TC52HC) |
| WLAN | FUSION_QA_2_1.3.0.011_Q |
| Zebra Bluetooth | 3.4 |

Revision History

| Rev | Description | Date |
|-----|-----------------------------------|--------------------|
| 1.0 | Initial release | September 22, 2020 |
| 1.1 | Add TC21 and TC26 Additional SKUs | October 14, 2020 |