

# Zebra MC18 Android L LifeGuard Update 17

# Release Notes - December 2021

# **Highlights**

This release contains the following software package which is compatible with the MC18 product. LifeGuard patches are cumulative and include all previous fixes that are part of earlier patch releases.

# **Software Packages**

Package Name	Package Description
CFE-MC18N0-L-V0-020902-N-00-17.zip	CFE package update software

# **LifeGuard Update 17:**

CFE-MC18N0-L-V0-020902-N-00-17.zip
 This CFE is applicable for 02-09-02-L-V0-M1 OS version.

> Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2021-12-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### Resolved Issues

- SPR45149 Fixed an Issue wherein on updating from LG5 to LG14/15/16 Mx Failure was seen.
- CVE 2021-1048 Patched the use-after-free security vulnerability which could allow code
  execution and local elevation of privilege to the kernel from an untrusted application. (SPR
  45273)

## **LifeGuard Update 16:**

> CFE-MC18N0-L-V0-020902-N-00-16.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version. The LG Patch includes the following updated components:

Android WebView - Version 93.0.4577.62

> Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2021-09-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/



#### **Resolved Issues**

 SPR41722 – Fixed an issue where the MC18 device would reboot when scan button is long pressed.

# **LifeGuard Update 15:**

CFE-MC18N0-L-V0-020902-N-00-15.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

> Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2021-06-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

# LifeGuard Update 14:

CFE-MC18N0-L-V0-020902-N-00-14.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

The LG Patch includes the following updated components:

Android WebView - Version 87.0.4280.141

Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2021-03-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

### **LifeGuard Update 13:**

CFE-MC18N0-L-V0-020902-N-00-13.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2020-11-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

# **LifeGuard Update 12:**

CFE-MC18N0-L-V0-020902-N-00-12.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version. The LG Patch includes the following updated components:

- MXMF Version 7.2.10.5 (For more detail please refer http://techdocs.zebra.com)
- > Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2020-08-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

### **Resolved Issues**



- SPR39558 Resolved an issue wherein MC18 was not able to retain wlan connection when kept idle for a longer duration.
- SPR38421/SPR37196/SPR37494 Resolved an issue where MC18 experiences slow Download speed in 802.11AC wave 2 enabled infrastructure.
- SPR38379 Resolved an issue wherein programmatic reboot via MX intermittently failed to perform device reboot.

# LifeGuard Update 11:

CFE-MC18N0-L-V0-020902-N-00-11.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2020-05-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### **Resolved Issues**

- SPR38988 Resolved and issue where the DHCP clientid values are displayed in getprop in special characters.
- SPR38198 Resolved an issue of the false battery over-temperature warnings at boot time, in a cradle, with a discharged battery.
- SPR38683 Resolved an issue wherein scanner stopped to work when soft trigger and hard trigger was used together.
- SPR37768 Resolved an issue where CPU utilization caused the device to become hot.

## **LifeGuard Update 10:**

> CFE-MC18N0-L-V0-020902-N-00-10.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

> Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2019-08-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### **Resolved Issues**

 SPR38013 - Resolved an issue where previously scanned data in past reappeared as valid scan data

### LifeGuard Update 09:

> CFE-MC18N0-L-V0-020902-N-00-09.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

> Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2019-06-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/



#### Resolved Issues

- SPR36598 Improvement added in WLAN driver to retain connection in a congested environment.
- SPR37246 Fixed an issue wherein logging used to get truncated with unexpected EOF error.
- SPR37196/SPR38421 Resolved an issue where MC18 experiences slow Download speed in 802.11AC wave 2 enabled infrastructure.

# LifeGuard Update 08:

CFE-MC18N0-L-XX-020902-N-00-08.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

The LG Patch includes the following updated components:

- MXMF Version 7.2.10.2 (For more detail please refer http://techdocs.zebra.com)
- Scanner Framework 19.53.37.0
- EKB: 1.7.0.5
- Bluetooth: 1.017.00
- Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2019-03-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### **Resolved Issues**

- SPR35368- Resolved an issue where in device is unable to scan barcode suspend and resume.
- SPR35362: Resolved and issue where in TC80 NGMS Scanner was not able to decode when HW picklist is enabled.
- SPR35288 Fixed an issue wherein initialization of scanner was taking ~1sec.
- SPR35054 Added support for reduced quite zone barcode decoding.
- SPR34844 Resolved an issue wherein multiple open calls are prevented when multiple application tries to open scanner without releasing previous instance.
- Updated below mentioned Components:

#### **LifeGuard Update 07:**

> CFE-MC18N0-L-XX-020902-N-00-07.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

> Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2018-12-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

## **LifeGuard Update 06:**

> CFE-MC18N0-L-XX-020902-N-00-06.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.



The LG Patch includes the following updated components:

- MXMF Version 7.2.9.0 (For more detail please refer <a href="http://techdocs.zebra.com">http://techdocs.zebra.com</a>)
- Enterprise Browser 1.8.0.0
- > Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2018-09-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### **Resolved Issues**

- SPR35025 Resolved an issue where Proxy Auto Config (PAC) did not work properly following stops/restarts of the PacService
- SPR33977 Resolved an issue wherein set time zone issue observed with StageNow.
- SPR34679 Resolved an issue wherein setting WiFi Band selection to Auto was not working properly with StageNow.
- Included Zebra Software License Manager v3.1.1.
- SettingsEULA has been renamed to Zebra Data Services.

# **LifeGuard Update 05:**

> CFE-MC18N0-L-XX-020902-N-00-05.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

The LG Patch includes the following updated components:

- MXMF Version 7.2.8.2 (For more detail please refer <a href="http://techdocs.zebra.com">http://techdocs.zebra.com</a>)
- EMDK Version 6.8.21.1121
- Staging Client Version 2.10.1.1389
- DataWedge Version 6.7.48
- Enterprise Keyboard Version 1.7.0.2
- Diagnostic Tool Version 1.15.0.11
- File Browser Version 1.19.1.2
- Android Security Patch Level: 2018-03-05 (Critical Patch Level: 2018-06-01).

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### **Resolved Issues**

- SPR33599 Resolved an issue wherein few system apps were being disabled after Applock whitelist mode was enabled.
- SPR33818 Fixed an issue wherein certain decoder type values were not persisting across a scanner enable/disable cycle.
- SPR33755 Resolved an issue wherein Whitelisted Apps were unable to submit XML to MX.
- SPR33207 Implemented Battery Health percentage values for PP+ batteries in the Device Diagnostic App.
- SPR33671 Resolved an issue wherein the profile creation used to fail if the username included "\" character.



- SPR34267 Resolved an issue where-in user was not able to enable USB debugging option using StageNow.
- SPR33862/33876 Fixed an issue where-in user could not set Display Timeout value of 30min using StageNow.
- SPR34145 Fixed an issue wherein user was unable to connect to WLAN network due to WEP Key Index issue.
- SPR34307/ SPR33607 Resolved an issue wherein devices out of the box intermittently failed to get staged via StageNow.
- SPR33981 Fixed an issue wherein Czech Republic could not be set as Regulatory country while configuring WLAN profile using StageNow.
- SPR34614 Fixed an issue in DataWedge wherein scanner could not be enabled due to quick enabling and disabling of scanner through Intents.
- SPR34804 Fixed an issue wherein applying MDM Lockdown profile used to fail on KK to L upgrade.
- SPR34805 Fixed an issue wherein user was unable to copy DW profiles to the autoimport folder via MDM on KK to L upgrade.
- SPR33920 Fixed an issue wherein devices failed to connect to WLAN network if the country selection is set to Japan.
- SPR34213 Resolved an issue wherein shared preference initialization without launching EKB.

# LifeGuard Update 04:

CFE-MC18N0-L- XX-020902-N-00-04.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

The LG Patch includes the following updated components:

- DataWedge Version 6.7.47
- Scanner Framework Version 18.10.15.00

#### **Resolved Issues**

- SPR33299/SPR33444 Resolved an issue wherein the device was not charged/powering off while in cradle.
- SPR34184 Resolved an issue wherein the Red LED Illumination beam gets stuck while using Scan Application.
- SPR34368 Resolved an issue wherein the Apps persist and storage memory was getting low on every reboot after ER/FR.
- SPR33973 Fixed an issue wherein scanner beam stuck off when pressing scanner button.
- SPR34529 Resolved an issue wherein the device reboot after a long pressing scanner button.
- SPR32700/SPR34548 Fixed an issue wherein the 802.11n MCS data rates were disabled to avoid interoperability issue.

## LifeGuard Update 03:

CFE-MC18N0-L-XX-020902-N-00-03.zip



This CFE is applicable for 02-09-02-L-V0-M1 OS version.

The LG Patch includes the following updated components:

- MXMF Version 7.2.0.6 (For more detail please refer <a href="http://techdocs.zebra.com">http://techdocs.zebra.com</a>)
- EMDK Version 6.8.20.1120
- Staging Client Version 2.10.1.1386
- DataWedge Version 6.7.34
- File Browser Version 1.19.1.2

### > Android Security Patch Level: 2018-03-05

Use the below link to see the Android Security bulletin for more information:

https://source.android.com/security/bulletin/

#### **Fixes**

- Spectre & Meltdown correction for variant 2.
- SPR33138 Resolved an issue wherein audio tool was not working on MC18 L due to permission issue.
- SPR33537 Resolved an issue wherein the device appears to be powering off while in cradle.
- SPR33538 Resolved an issue wherein scanner beam stuck off when pressing scanner button.
- SPR33639 Resolved an issue wherein the device stops emitting scan beam after waking up from suspend.

# LifeGuard Update 02:

CFE-MC18N0-L-XX-020902-N-00-02.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.

The LG Patch includes the following updated components:

- MXMF Version 7.1.1.0 (For more detail please refer http://techdocs.zebra.com)
- DataWedge Version 6.6.49
- EMDK Version 6.7.10.1010
- Staging Client Version 2.9.1.1344

# > Android Security Patch Level: 2017-12-05

Use the below link to see the Android Security bulletin for more information:

https://source.android.com/security/bulletin/

# **Resolved Issues**

- SPR33233 Resolved an issue wherein the DataWedge 6.2.24 could not replace separator or non-printable ascii character with \$.
- SPR32463 Resolved an issue wherein the StageNow File Manager downloads frequently fails due to Socketimeout exception.
- SPR32676 Resolved an issue wherein DataWedge crashes due to velocity application profile creation.

## LifeGuard Update 01:

> CFE-MC18N0-L-XX-020902-N-00-01.zip

This CFE is applicable for 02-09-02-L-V0-M1 OS version.



## > Android Security Patch Level: 2017-07-05

Use the below link to see the Android Security bulletin for more information: https://source.android.com/security/bulletin/

#### **Fixes**

- Corrections for KRACK vulnerabilities applied.
- SPR33137 Updated EB v1.7.1
- SPR31340 -- Added support to enable/disable Network Monitoring Notification.
- SPR32731 -- Resolved an issue wherein EMDK crash was observed.

# **Device Compatibility**

This software release has been approved for Android MC18 models mentioned below.

Device	Operating System
MC18	Android 5.1.1

# **Important Links**

- Requirements and Instructions
  - o Installation and setup instructions
- Zebra Techdocs
- Developer Tools

# **Component Version Info**

Component / Description	Version
Build Number	02-09-02-L-V0-M1
Device Patch Version	17
Android version	5.1.1
Android_SDK_Level	22
Android Security Patch Level	2018-03-05 (Critical Patch Level: 2021-12-01)
OSX	TI.51.5.2.13
Linux_kernel	3.4.48
Wifi	FUSION_A_5.00.0.031



	Application: A_5.00.0.0.004 Middleware: A_5.00.0.0.5 Radio: A_5.00.0.0.12
X_loader	1.41.0(2017-Oct-9)
U_boot	1.1.5(2017-Oct-9)
Platform	TI - omap4430- 4AJ22
Scanning_Framework	19.58.37.1
DWDemo	2.0.13
MXMF	7.2.10.5
EA	3.62
SSPAM	4.7
Touch	Atmel mXT224
Bluetooth_Stack	01.025.00
Partation_table	NA
Flash_Size	4G
RAM_Size	1G
GPS	NA
MMS	NA
RIL_Version	NA
MSP_Agent_RD	7.08.86
Datawedge	6.7.51
RxLogger Utility	4.58.5.0
StageNow	2.10.1.1389



B2M_Elemez	1.0.0.352
Data_Analytics	3.7.1.1002
EnterpriseBrowser	1.8.0.0
App_Gallery	3.0.1.7
SOTI	12.2.0 Build 23469
EMDK	6.8.24.1124
Zebra Volume Control (ZVC)	1.1.23
File_browser	1.19.1.2
BatteryManager	1.3.7
Device Diagnostic tool	1.15.0.11
WorryFreeWiFi (SMART MU)	2.3.3 App-2.3.7
Enterprise Keyboard (EKB)	1.7.0.5
Zebra Software License Manager	3.1.1
Zebra Data Services	1.0.0.1002
WebView	87.0.4280.141
Image Kit	IMGKIT_8.02T01.18

Last Revised: <27-12-2021>